


Work Detail's

Name of work : Repairs to recoil unit & idler group of JCB JS 80 No 109482

Sr. No.	Description	Qty	Unit	Rate	Amount
1	2	3	4	5	6
	Repairs to recoil unit of JCB JS 80 No. 109482 by removing the track chain assly from machine, checking and removing wornout parts, providing & fitting new spares as per OEM specification				
A	Cost of Spare Parts				
1	331/20045 - Yoke Idler	1	No		
2	331/20048 - Bracket	2	No		
3	998/10443 - Kit Seal (JS75)	1	No		
4	904/20188 - Seal (JS75)	1	No		
5	904/20190 - Seal (JS75)	1	No		
6	904/20189 - (JS75)	2	No		
7	826/10579 - Pin	2	No		
8	25/964902 - Solenoid Coil (JS75)	1	No		
				Total A	
B	Cost of Labour Charges				
1	Dismantling Track chain by removing master pin/No. (UC/01)	1	Job	843.00	
2	Reassembling of track chain & fitting of master pin by hydraulic press after repair (UC/15)	1	Job	883.00	
3	Reconditioning to grouser shoe web by welding with special electrodes & filling to std. size including material (UC/16)	5	Job	647.00	
				Total B	
				Total A + B	
				SGST 9%	
				CGST 9%	
				Grand Total	
				Say Amount	


P.L. Hadule
Deputy Engineer
Mechanical Subdivision No.2
Dharashiv