

Work Detail's

Name of work : Repairs to Swing Motor Assly of JCB Js - 80 Excavator No.109482

Sr.	Description	Qty	Unit	Rate	Amount
1	2	3	4	5	6
Repairs to swing motor assly of JCB JS - 80 Excavator No.109482 by dismantling the swing motor, cleaning, checking wear & tear of parts and replacing the following damaged & worn out parts & providing and fitting new spare parts to machine as per OEM specification					
A	Cost of Spare Parts				
1	LTM0181 BEARING (JS75)	1	No		
2	LMM0485 PLATE	1	No		
3	LMM0486 PLATE	1	No		
4	LTM0182 BEARING (JS75)	1	No		
5	LBQ5253 O RING JS 75	1	No		
6	LMM0590 PISTON	2	No		
7	LMM0588 RING,TEFLON	2	No		
8	UBJ0382 PLUG	2	No		
9	LKM0118 BUSH	4	No		
10	LMM0587 RING,TEFLON	4	No		
11	LAM0051 RING	1	No		
	Total A				
B	Cost of Labour Charges				
1	Overhauling of swing motors by dismantling, cleaning and inspection of parts, reassembling etc. A/12	1	Job		
	Total B				
	Total A + B				
	SGST 9%				
	CGST 9%				
	Grand Total				
	Say Amount				


 Deputy Engineer
 Mechanical Subdivision No.2,
 Dharashiv