

WORK DETAILS

Name of work : Repairs to Bucket Assly of Tata Hitachi 120H No. 52473 by removing old damaged Tooth Point & burst leaked Hyd.Hose

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repairs to Bucket Assly of Tata Hitachi 120H No. 52473 by removing old damaged Tooth Point & brust leaked Hyd.Hose by way of supplying Following Spare parts as per OEM Specification & part number given below.					
A	Providing & fitting following spares as per OEM Specification					
1	TB00286	TOOTH TIP	5	No.		
2	TE00162	Key	5	No.		
3	TE00163	KEY LOCK	5	No.		
4	2015428	CUTTER:SIDE RH	1	No.		
5	2015429	CUTTER:SIDE LH	1	No.		
6	4332827	HOSE	1	No.		
B	LABOUR CHARGES					
1	Repairs to bucket by replacing the teeth for excavators / No		5	Job		
2	Replacing side cutter of bucket / No		2	Job		
3	Removing & refitting high pressure hose assly.		1	Job		
					GST 18%	
					Total Rs	



Deputy Engineer
Mechanical Subdivision, Latur