

WORK DETAILS

Name of work : Repair to Travel Piping (LC Track) ,Lubricate piping & Front Piping of Tata Hitachi Ex350-402.

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repair to Tata Hitachi Ex350-402 by replacing Hoses, Clip band & Seal Dust etc. as per OEM Specification & part number given below.					
A	Providing & fitting following spares as per OEM Specification					
1	4317865	Hose	1	No.		
2	4377481	Hose	1	No.		
3	4121859	Clip Band	2	No.		
4	4257291	Hose	1	No.		
5	4085479	Seal Dust	2	No.		
6	8069385	Pipe	1	No.		
B	LABOUR CHARGES					
1	Removing and refitting high pressure hose assembly		4	Job		
					GST 18%	
					Total Rs	



**Deputy Engineer
Mechanical Subdivision, Latur**