

Work Details

Name of work :- Repair & Reconditioning to Track Adjuster Assly (RH Side) of TATA Hitachi Zx 220 H
No. 305

Sr. No.	Description		Qty	Unit	Rate Rs	Amount
1	2	3	4	5	6	7
	Repair & Reconditioning to Track Adjuster Assly(RH Side) of TATA Hitachi Zx 220 H No. 305. by repairs to following spares parts as per OEM Specification of given below.					
A	Cost of Spares Charges					
1	4430474	Spacer	1	No.		
2	3084581	Washer	1	No.		
3	3088026	Road (Piston)	1	No.		
4	4430469	Ring Wear	1	No.		
5	4430467	Packing	1	No.		
6	4430468	Seal Dust	1	No.		
7	4412710	Nut	1	No.		
8	4445998	Ring Wear	1	No.		
	Total of Spares Rs :-					
B	Cost of Labour Charges					
1	Dismantling Track chain by removing master pin/No. (UC/01)		1	Job		
2	Repairs to track adjuster/recoil cylinder by replacing seal kit (UC/12)		1	Job		
3	Reassembling of track chain & fitting of master pin by hydraulic press (UC/15)		1	Job		
	Total of Labour Rs :-					
	Total Spares+Labour Rs :-					
	CGST 9 % Rs :-					
	SGST 9 % Rs :-					
	Grand Total Rs :-					
	Round Off Rs :-					



(S.S.Garad)
Deputy Engineer
Mechanical Subdivision No. 3,
Dharashiv