## **ENQUIRY**

## Name of work: Repairs to undercarriage system Track Roller Group & Hydraulic System of BEMI BE-200 excavator No.10076.

of BEIN BE 200 CACAMADO 110.10070.				
Sr. No.	Description		Qty	
	Repairs to undercarriage system Track Roller Group & Hydraulic System of BEMI BE-200 excavator No.10076. by removing old damaged parts from machine & replacing fitting new as per OEM specification & part no.given below with test and trial @ site.			
A	Cost of Spares Charges			
1	781TF02038	Track Roller	1	Nos
2	781PH02409	Pipe assly.	1	Nos
3	781PH02936	Pipe assly.	1	Nos
4	781PH02563	Pipe assly.	1	Nos
В	Cost of Labour Charges			
1	(UC/01)	Dismantling Track chain by removing Master Pin / Master Link bolts.	1	job
2	(UC/04)	Track Roller Removing refitting to chasis	1	jobs
3	(UC/15)	Reaseembling track chain by fitting master pin	1	job
4	(H/06)	Removing & refitting high Pressure Hoses/Pipe assly.	3	job

Tarana .

G.S.Giram
Deputy Engineer
Mech. Sub Division ( L.T.P )
Latur