

### WORK DETAILS

*Name of work : Repair & Reconditioning RH Track Chain Assly of Tata Hitachi EX350 No 0402*

Sr. No.	Part Details		Qty	Rate	Amount		
	Part Number	Description					
	Repair & Reconditioning RH Track Chain Assly of Tata Hitachi EX350 No 0402 by removing the assly from machine, dismantling ,checking and removing unserviceable parts & replacing by new spares . Also removing bushing of bucket link assly & replacing by new spares as per OEM Specification						
A	Providing & fitting following spares as per OEM Specification						
1	4378891	Pin	3	No			
2	3077928	Bushing	4	No			
3	4378892	Seal Dust	8	No			
4	3081343	Bolt	12	No			
5	3081344	Nut	12	No			
B	<b>LABOUR CHARGES</b>						
1	Dismantling Track chain by removing Master Pin / Master Link bolts		1	Job			
2	Removing and replacing link/ Bush		3	Job			
3	Reassemble track chain by fitting master pin		1	Job			
<b>GST 18%</b>							
<b>Total Rs</b>							



**Deputy Engineer**  
**Mechanical Subdivision, Latur**