

WORK DETAILS

Name of work : Repair & Reconditioning to Idler Assy of Tata Tipper No. MH 20 CU 0195

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repair & Reconditioning to Front Spring Suspension Assy Fuel Injection Pump of Tata Tipper No. MH 20 CU 0195by removing the assly from machine,dismentling checking and removing unservicable parts & replacing by new spares . Also removing bushing of bucket link assly & replacing by new spares as per OEM Specification					
A	Providing & fitting following spares as per OEM Specification					
1	206732100111	ASSY First Leaf With Bush	1	No.		
2	206732107132	Second Leaf	1	No.		
3	206732107134	Fourth Leaf	1	No.		
4	206732107136	Sixth Leaf	1	No.		
5	252507140164	Kit HP Lines Rotary PUMP	1	No.		
6	252509140811	HOSE Top AT AIR Filter Inlet	1	No.		
7	252513100126	CYL Head Assy	1	No.		
8	252513103707	CYL Sleeve A/C STD94D	1	No.		
9	252514603820	Alluminium Pipe TC to IC	1	No.		
10	252514603821	AL Pipe Intercooler to Engine	1	No.		
11	252520156306	V BeltCOGGED 325 MM Long	2	No.		
12	252520140116	AssyFan	1	No.		
B	LABOUR CHARGES					
1	Front spring leaf assly. removing, dismantling, recambering and refitting / Assy		1	Job		
2	Removing & refitting high pressure hose assembly		1	Job		
3	Radiator chock up removing by cleaning all the tubes, soldering the tubes with top & bottom removing and refitting		1	Job		
					GST 18%	
					Total Rs	



Deputy Engineer
Mechanical Subdivision, Latur