Work Details

Name of work: Repair to Mahindra Bolero pickup MH 25 P 5123 by replacing filters ,Hoses, Clutch assy, Leaf spring front & rear Assy. etc.

Sr. No.	Part Details			Qty / Unit		Rate	Total
	Pa	art Number	Description				
	,Hoses, Clu		ckup MH 25 P 5123 by way of supplying filters g front & rear Assy. etc. as per OEM Specification &				
A	Providing & fitting following spares as per OEM Specification						
1	0801BA0285N		CLUTCH DRIVEN PLATE ASSY(F491)	1	No		
2	0706AD1730N		BOTTOM LEVER MAXX	1	No		
3	0706AAD02270N		GEAR SHIFT LEVER	1	No		
4	0313AB1960N		AIR FILTER ASSEMBLY	1	No		
5	0313AAB02510N		HOSE ASSY AIR CLEANER (CLEAR SIDE)	1	No		
6	0313AC0280N		AIR ELEMENT	1	No		
7	9.	420000073	OIL FILTER CARTRIDGE (OPTIONAL	1	No		
8	1001CAA15521N		FUEL FILTER ASSY	1	No		
9	1001FAA00561N		TANK MODULE ASSY DELPHI	1	No		
10	0401AAA02680N		LEAF SPRING ASSY REAR	1	No		
11	0402BA0281N		SHOCK ABSORBER REAR	1	No		
12	0401ACG00010N		LEAF SPRING ASSY FRONT	1	No		
13	0403	3ABG00041N	SHOCK ABSORBER FRONT	1	No		
					(Cost of Spares Rs :	
В	Labour Charges (as per Mechanical Job work Schedule Rate 2019-2020) :						
1	C/01	Clutch unit complereplacing necessar	ete dismantling, leaning, checking, overhauling by y parts	1	No		
2	SU/01	Front spring leaf a refitting / Assy.	ssly. Removing, dismantling, recambering and	1	No		
3	SU/02	Rear spring leaf as Assy.	ssy. removing, dismantling, recambering and refitting /	1	No		
4	SU/08	Shock absorber fitting / No.		2	No		
5	BD/11	Complete flooring rusted portion cutting and new flooring pieces patching & welding including material.		1	No		
6	H/06 Removing & refitting high pressure hose assembly(Similar to excavator)			1	No		
					Cost of Labour Rs : Cost of Spares + Labour Rs :		
	CGST 9%						
	SGST 9% Grand Total Rs :						