


Work Details

Name of work :- Repairs to Hydraulic assly & Water Pump Assembly of TATA Hitachi 120 H Ex No. 51578

Sr. No.	Part No.	Description	Qty	Unit	Rate Rs	Amount
1	2	3	4	5	6	7
	Repairs to Water Pump Assembly of TATA Hitachi 120 H Excavator No. 51578 as per OEM Specification given below.					
A	Cost of Spares Charges					
1	4440813	Fan Belt (Old - 4448370)	1	No.		
2	897253-0281	Pump Assly Water Pump	1	No.		
3	9149507	Hose	1	No.		
	Total of Spares Rs :					
B	Cost of Labour Charges					
1	Replacing water pump assembly. (E/50)		1	Job		
2	Removing & refitting high pressure hose assly. (H/06)		1	Job		
	Total of Labour Rs :					
	Total of Spares + Labour Rs :					
	CGST 9 % Rs :					
	SGST 9 % Rs :					
	Grand Total Rs :					
	Round Off Rs :					


 (S.S. Garad)
 Deputy Engineer
 Mechanical Sub Division No.3,
 Dharashiv