

Work Details

Name of work :- Repairs & reconditioning Boom Cylinder assly (LH Side) of Tata Hitachi 120 H No. 52466

Sr. No.	Part No.	Description	Qty	Unit	Rate	Amount
1	2	3	4	5	6	7
	Repairs & reconditioning Boom Cylinder assly (LH Side) of Tata Hitachi 120 H No. 52466 as per OEM specification given below.					
A	Cost of Spares Charges					
1	TC 01374/39	Boom Cylinder Kit	1	No.		
2	TC 01374/5	Pistone Rod Nut	1	No.		
3	TC 01374/8	Pipe SA	1	No.		
4	TC 01374/7	Bush	1	No.		
					Total A Rs :-	
B	Cost of Labour Charges					
1	Dismantalling & refitting Hoist/Boom assy. after repairs.		1	Job		
2	Dismantling of jack assly., cleaning, inspection and replacement of seals with test & tria.		1	Job		
					Total B Rs :-	
					Total A+ B Rs :-	
					CGST 9 % Rs :-	
					SGST 9 % Rs :-	
					Grand Total Rs :-	
					Round Off Rs :-	



(S.S. Garad)

Deputy Engineer

Mechanical Subdivision No.3,

Dharashiv