

# Work Detail's

**Name of work :- Repair Reconditioning to Travel Device (LH Side) Of Tata Hitachi 120 H No.52474**

Sr. No.	Description	Qty	Unit	Rate Rs	Amount
1	2	3	4	5	6
	Repair Reconditioning to Travel Device(LH Side) Of Tata Hitachi 120 H No.52474 following spares parts as per OEM Specification of given below.				
<b>A</b>	<b>Cost of Spares Charges</b>				
1	4436242	Pin Knock	1	No.	
2	3085566	Gear Planetary	3	No.	
3	4192982	Plate Thrust	12	No.	
4	4144020	Pin Spring	3	No.	
5	3085569	Gear Sun	1	No.	
6	4418771	Spacer	1	No.	
7	4192020	Pin Spring	3	No.	
8	4442788	Bearing Niddle	3	No.	
9	4245797	Plug- P 001/2	3	No.	
10	3094907	Gear Planetary	1	No.	
11	4609016	Bolt Sems	12	No.	
	<b>Total of Spares Rs :-</b>				0.00
<b>B</b>	<b>Cost of Labour Charges</b>				
1	A/11 Overhauling of track motors by dismantling, cleaning and inspection of parts, reassembling etc.		1	Job	
	<b>Total of Labour Rs :-</b>				0.00
	<b>Total Spares+Labour Rs :-</b>				0.00
	<b>CGST 9 % Rs :-</b>				0.00
	<b>SGST 9 % Rs :-</b>				0.00
	<b>Grand Total Rs :-</b>				0.00
	<b>Round Off Rs :-</b>				0.00

  
 ( P.L.Hadule )  
 Deputy Engineer  
 Mechanical Subdivision No. 2,  
 Dharashiv