

Work Details

Name of work : Repair & reconditioning of Track Adjuster Assly (RH & LH Side) of TATA Hitachi Zx120 52475.

Sr. No.	Part Details		Qty / Unit		Rate	Total
	Part Number	Description				
	Repair & reconditioning of Track Adjuster Assly (RH & LH Side) of TATA Hitachi Zx120 52475. by dismantaling Track Chain by removing master pin, Replacing Track Adjuster by replacing Oil Seal & unservicable spares with new parts as per OEM Specification					
A	Cost of Spares Charges					
1	3098282	Spring	1	No		
2	4182361	Ring Wear	2	No		
3	4179303	Packing O'ring	2	No		
4	4449766	Ring Wear	1	No		
5	4413075	Seal Dust	2	No		
6	4255055	Valve	1	No		
Total of Spares Rs :-						
B	Cost of Labour Charges					
1	Dismantling Track chain by removing master pin/No.		2	Job		
2	Repairs to track adjuster/recoil cylinder by replacing seal kit.		2	Job		
3	Reassembling of track chain & fitting of master pin by hydraulic press.		2	Job		
	Total of Labour Rs :-					
	Total of Spares + Labour Rs :-					
	CGST 9% :-					
	SGST 9% :-					
	Grand Total Rs :-					
	Round Off Rs :-					



(S.S.Garad)

Deputy Engineer

Mechanical Subdivision No. 3,
Dharashiv