

**WORK DETAILS**

***Name of work : Repairs to Bucket Assly of Tata Hitachi 120H No. 52806 by removing old damaged Tooth Point & burst leaked Hyd.Hose***

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repairs to Bucket Assly of Tata Hitachi 120H No. 52806 by removing old damaged Tooth Point & brust leaked Hyd.Hose by way of supplying Following Spare parts as per OEM Specification & part number given below.					
A	Providing & fitting following spares as per OEM Specification					
1	TB00286	TOOTH TIP	5	No		
2	TE00162	Key	5	No		
3	TE00163	KEY LOCK	5	No		
4	2015428	CUTTER:SIDE RH	1	No		
5	2015429	CUTTER:SIDE LH	1	No		
6	4332827	HOSE	1	No		
B	LABOUR CHARGES					
1	Repairs to bucket by replacing the teeth for excavators / No		5	Job		
2	Replacing side cutter of bucket / No		2	Job		
3	Removing & refitting high pressure hose assly.		1	Job		
					Sr. No.	
					Total Rs	

**Deputy Engineer**  
**Mechanical Subdivision, Latur**