

MEASUREMENT SHEET


Name Of Works :- Repairs & reconditioning to Idler Wheel Assembly RH Side Of Tata Hitachi
120H No. 52475


Sr. No	Description	Qty	Rate	Amount
A	Repairs & reconditioning to Idler Wheel Assembly RH Side Of Tata Hitachi 120H No. 52475			
1.	Dismantling the track Chain by removing Mater Pin / Master Link, Bolts	1Job.	1116.00	1116.00
B	Replacing the following spare parts & Providing & Fitting New Spare Parts as per OEM specification given below			
1	1020173 – Bearing	2No.	4986.00	9972.00
2	3035618 – Axle	1No.	10322.00	10322.00
3	4153468 – Seal Group	2No.	3414.00	6828.00
4	TD 00673 – Bushing	2No.	1497.00	2994.00
5	1026807 – Yoke	1No.	3919.00	3919.00
6	4255804 – Pin	2No.	281.00	562.00
D	Repairs to Inner Bore of Idler by welding & Turning to STD Size Bore, Tapping etc	1Job.	4008.00	4008.00
E	Removing & refitting of Idler Assembly	1Job.	1191.00	1191.00
F	Reassembling of Track Chain and Fitting of Master Pin by Hyd. Press	1Job.	1119.00	1119.00
				41,231.00
			CGST 9%	3,711.00
			SGST 9%	3,711.00
			NET TOTAL =	48,653.00

(Rs. Forty Eight Thousand Six Hundred Fifty Three Rupees Only)

CERTIFICATE

- 1) Repairs are essential to keep machine in good working condition.
- 2) Spares are not available in dept. store
- 3) Such type of repair job are not carried out in dept. work shop due to lack & facilities.
- 4) Rates are reasonable.


B.V Satpute
Sectional Engineer


Deputy Engineer
Mechanical Sub Divn No.3
Osmanabad