

**WORK DETAILS**

**Name of work : Repair & Reconditioning Center Joint Assy of Tata Hitachi 120 Hydraulic Exc No. 52473**

| Sr. No. | Part Details   |             | Qty |     | Rate            | Amount |
|---------|--|-------------|-----|-----|-----------------|--------|
|         | Part Number  | Description |     |     |                 |        |
|         | Repair & Reconditioning Center Joint Assy Assly of Tata Hitachi 120 Hydraulic Exc No. 52473 by removing the Center Joint Assy assly from machine,dismantling ,checking and removing unservicable parts & replacing by new spares . Also removing bushing of assly & replacing by new spares as per OEM Specification |             |     |     |                 |        |
| A       | Providing & fitting following spares as per OEM Specification  |             |     |     |                 |        |
| 1       | 4410066  | BUSHING     | 1   | No. |                 |        |
| 2       | 4410446  | O RING      | 1   | No. |                 |        |
| 3       | 4406165  | SEAL OIL    | 6   | No. |                 |        |
| 4       | 3070250  | RING        | 1   | No. |                 |        |
| B       | <b>LABOUR CHARGES</b>  |             |     |     |                 |        |
| 1       | Center Joint overhauling.  |             | 1   | Job |                 |        |
| 2       | 4333700  | HOSE AASY   | 1   | No. |                 |        |
| 3       | Removing refitting to High Pressure Hose Assy  |             | 1   | Job |                 |        |
|         |  |             |     |     | <b>GST 18%</b>  |        |
|         |  |             |     |     | <b>Total Rs</b> |        |



**Deputy Engineer  
Mechanical Subdivision, Latur**