

Work Detail's

Name of work : Repairs to Tata Hitachi Ex-200 No.8680

Sr. No.	Description	Part No	Qty	Unit	Rate	Amount
1	2	3	4	5	6	7
	Repairs to Bucket Cylinder Assly of Tata Hitachi Ex-200 No.8680 by replacing following worn out & unservicable spares by new one including cost of spares & Labour charges with test & rtial on site					
A	Part Of Spares					
1	H.E.Cover	TD00719/4	1	No		
2	Seal Kit	TD00719/41	1	No		
					Total A	
B	Cost Of Labour Charges					
1	Removing Bucket /Arm/Boom Jack Assly from machine and refitting after repairs	H/08	1	Job		
2	Dismantling of Jack assly, cleaning, inspection and replacement of seal with test & trial	H/09	1	Job		
					Total B	
					Total A+B	
					SGST @ 9%	
					CGST @ 9%	
					Say Total	
					Grand Total	


P.L. Hadule
Deputy Engineer
Mechanical Subdivision No.2
Dharashiv