

Work Details

Name of work : Repairs to Idler Assly RH Side Tata Hitachi Ex-200 No.8680

Sr. No.	Description	Part No	Qty	Unit	Rate	Amount
1	2	3	4	5	6	7
	Repairs to Idler Assly RH Side by providing & fitting following spares by new one for replacement of damaged items of Tata Hitachi Ex-200 No.8680					
A	Part Of Spares					
1	1005809	YOKE	1	No		
2	3022642	AXLE	1	No		
3	A810070	O-RING 1AGO70	2	No		
4	TE02713	BUSHING	2	No		
5	4126209	PIN 18.0X10M.0	2	No		
6	4317587	SEAL GROUP (Old 4153731)	2	No		
Total A						
B	Cost Of Labour Charges					
1	Removing & refitting of idler assembly UC/08		1	Job		
2	Radiator chock up removing by cleaning all the tubes, soldering the tubes with top & bottom removing and refitting (E/46)		1	Job		
Total B						
Total A+B						
SGST @ 9%						
CGST @ 9%						
Say Total						
Grand Total						


P.L. Hadule
Deputy Engineer
Mechanical Subdivision No.2
Dharashiv