

Work Details

Name of work : Repair & reconditioning of Track Adjuster Assly (RH & LH Side) of TATA Hitachi Zx120 51573.

Sr. No.	Description		Qty / Unit	Rate	Total
	Repair & reconditioning of Track Adjuster Assly (RH & LH Side) of TATA Hitachi Zx120 51578. by dismentaling Track Chain by removing master pin, Replacing Track Adjuster by replacing Oil Seal & unservicable spares with new parts as per OEM Specification				
A	Cost of Spares Charges				
1	3098282	Spring	1	No	
2	4182361	Ring Wear	2	No	
3	4179303	Packing O'ring	2	No	
4	4449766	Ring Wear	1	No	
5	4413075	Seal Dust	2	No	
6	4255055	Valve	1	No	
Total of Spares Rs :-					
B	Cost of Labour Charges				
1	Dismantling Track chain by removing master pin/No.		2	Job	
2	Repairs to track adjuster/recoil cylinder by replacing seal kit.		2	Job	
3	Reassembling of track chain & fitting of master pin by hydraulic press.		2	Job	
Total of Labour Rs :-					
Total of Spares + Labour Rs :-					
CGST 9% :-					
SGST 9% :-					
Grand Total Rs :-					
Round Off Rs :-					



(G.S.Giram)
Deputy Engineer
 Mechanical Subdivision (LTP)
 Latur

