

ENQUIRY

Name of work : *Repair to L.H SideTrack chain Assembly of JCB JS 140 Sr No 2439386 .*

Sr. No.	Part Details		Qty.	
	Part Number	Description		
	Repair to L.H.Side Track chain Assembly of JCB JS 140 Sr No 2439381 by Providing & fitting Following spares with complete test & trial at site.			
A	a) List of Spares			
1	331/21731	Seal Dust	20	Nos
2	331/17179	Pin Track	25	Nos
3	331/21733	Bush Track	20	Nos
4	JNA0085	Bolt Track Plate	60	Nos
5	331/17177	Link Track LHS	12	Nos
B	Cost of Labour Charges			
1	UC/01 -Dismantling Track chain LH side by removing Master Pin .-		1	Job
2	UC/13 -Removing & refitting new link bush, pin of track chain/Set (inner & outer)		1	Job
3	UC/15 -Reassembling of track chain LH side & fitting of master pin by hydraulic press.		1	Job



G.S.Giram
Deputy Engineer
Mech. Sub Division (L.T.P)
Latur