

WORK DETAILS

Name of work : *Repair & Reconditioning RH Track Chain Assly of Tata Hitachi 120 Hyd Exc No.52473*

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repair & Reconditioning RH Track Chain Assly of Tata Hitachi 120 Hyd Exc No.52473by removing the assly from machine,dismentling checking and removing unserviceable parts & replacing by new spares . Also removing bushing of bucket link assly & replacing by new spares as per OEM Specification					
A	Providing & fitting following spares as per OEM Specification					
1	TD04783/06	TRACK BUSHING	5	No.		
2	TD04783/04	TRACK PIN	5	No.		
3	TD04783/08	DUST SEAL	10	No.		
4	TD04783/11	TRACK BOLT	20	No.		
5	TD04783/12	TRACK NUT	20	No.		
6	TD04783/05	TRACK MASTER PIN	1	No.		
7	TD04783/09	SPACER	2	No.		
B	LABOUR CHARGES					
1	Dismantling Track chain by removing Master Pin / Master Link bolts.		1	Job		
2	Removing and replacing link/ Bush		5	Job		
3	Reaseembling track chain by fitting master pin		1	Job		
4	Alternator overhauling & refitting.		1	Job		
					GST 18%	
					Total Rs	



Deputy Engineer
Mechanical Subdivision, Latur