

WORK DETAILS

Name of work : Repair & Reconditioning LH Track Adjuster Assly of Tata Hitachi 120 Hyd Exc No.52473

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repair & Reconditioning LH Track Adjuster Assly of Tata Hitachi 120 Hyd Exc No.52473 by removing the assly from machine,dismtentling checking and removing unservicable parts & replacing by new spares replacing by new spares as per OEM Specification					
A	Providing & fitting following spares as per OEM Specification					
1	4413075	SEAL DUST	1	No.		
2	4357539	NUT	1	No.		
3	3098282	SPRING	1	No.		
4	4360347	O RING	1	No.		
5	4179303	PACKING O RING	1	No.		
6	4182361	RING WEAR	1	No.		
7	4449766	RING WEAR	1	No.		
B	LABOUR CHARGES					
1	Dismantling Track chain by removing Master Pin / Master Link bolts.		1	Job		
2	Repairs to track adjuster/recoil cylinder by replacing seal kit		1	Job		
3	Reaseembling track chain by fitting master pin		1	Job		
1	4219356	HOSE AASY	1	No.		
4	Removing & refitting high pressure hose assembly		1	Job		
GST 18%						
Total Rs						



Deputy Engineer
Mechanical Subdivision, Latur