


## Work Detail's

Name of work :Repairs To Boom Jack & Bucket Jack by replacing seal kit of JCB JS 80 No.109485

Sr.	Description	Qty	Unit	Rate	Amount
1	2	3	4	5	6
	Repairs To Boom Jack & Bucket Jack by replacing seal kit of JCB JS 80 No.109485 by providing & fitting as per OEM specification & part number given below.				
<b>A</b>	<b>Cost of Spare Parts</b>				
1	130/15245 SEAL KIT-BOOM RAM 5D	1	No		
2	332/Y6195 Seal Kit(DONG-BUCKET)	1	No		
3	334/F3999 BOOM HOSE ROLLER	1	No		
4	335/E9510 BUSH	1	No		
5	02883/51791 HOSE	1	No		
6	02/630879 Hose	1	No		
	<b>Total A</b>				
<b>B</b>	<b>Cost of Labour Charges</b>				
1	Removing bucket/arm/boom jack assly. from machine and refitting after repairs H/08	1	Job		
2	Dismantling of jack assly., cleaning, inspection and replacement of seals with test & trial H/09	1	Job		
3	Removing & refitting high pressure hose assly.H/06	2	Job		
4	Fuel tank opening cleaning, brazing & refitting E/43	1	Job		
	<b>Total B</b>				
	<b>Total A + B</b>				
	<b>SGST 9%</b>				
	<b>CGST 9%</b>				
	<b>Grand Total</b>				
	<b>Say Amount</b>				

  
**Deputy Engineer**  
**Mechanical Subdivision No.2,**  
**Dharashiv**