

WORK DETAILS

Name of work : *Repair to Hydraulic system (Side branch piping ,Delievery piping) Tata Hitachi Zaxis 120 Excavator No. 52806*

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repair to Hydraulic system (Side branch piping ,Delievery piping) Tata Hitachi Zaxis 120 Excavator No. 52806 by removing old & damaged burst leaked Hyd.Hose from machine & replacing fitting new Hyd.Hose as per OEM specification & part no.given below with test and trial @ site.					
A	Providing & fitting following spares as per OEM Specification					
1	4285801	HOSE	1	No.		
2	4250063	HOSE	1	No.		
3	4455403	HOSE	1	No.		
B	LABOUR CHARGES					
1	Removing & refitting high pressure hose assly.		3	Job		
					GST 18%	
					Total Rs	



Deputy Engineer
Mechanical Subdivision, Latur