


Work Detail's

Name of work :- Repair & Reconditioning to General Assly Of Covering Parts of Sany 140 Excavator No.14381211

Sr. No.	Description		Qty	Unit	Rate Rs	Amount
1	2	3	4	5	6	7
	Repair & Reconditioning to General Assly Of Covering Parts of Sany 140 Excavator No.14381211 by repairs to following spares parts as per OEM Specification of given below.					
A Cost of Spares Charges						
1	13073169	Left Upper Rear Cover Plate	1	No.		
2	60060548	Washer	44	No.		
3	A210111000202	Bolt	26	No.		
4	A210111000342	Bolt	8	No.		
5	A222200000065K	Locking Equipment SY200C1.1.6.4.2.	2	No.		
6	24000639	Washer	7	No.		
7	13073602	Middle Upper Cover Plate	1	No.		
8	A210111000101	Bolt	58	No.		
9	12236268	Trim cover SY135C9I2K.1.6.13	1	No.		
Total of Spares Rs :-						
B Cost of Labour Charges						
1	BD/03 Front bumper removing, repairing by welding, straightening, denting & refitting (Equivalent to Tata LPK2518)		1	Job		
Total of Labour Rs :-						
Total Spares+Labour Rs :-						
CGST 9 % Rs :-						
SGST 9 % Rs :-						
Grand Total Rs :-						
Round Off Rs :-						


 (P.L.Hadule)
 Deputy Engineer
 Mechanical Subdivision No. 2,
 Dharashiv