

Work Details

Name of work : Supply & Repairs Of Spares For Mahindra Transportor MH 25 U 1481

Sr. No.	Description	Part No	Qty	Unit	Rate	Amount
1	2	3	4	5	6	7
	Supply & Repairs Of Spares For Mahindra Transportor MH 25 U 1481 by repairs to following spares parts as per OEM Specification of given below.					
A	Spare Parts					
1	6802DAP00161N	CLUTCH BOOSTER ASSEMBLY	1	No		
2	6402DAB00021N	Element Safety Air	1	No		
3	6802AAP00031N	BEARING CLUTCH RELEASE	1	No		
4	6801BAU00021N	CLUTCH DISC ASSEMBLY DIA 395 mm	1	No		
5	0401AA0750N	LEAF SPRING ASSY FRT	2	No		
					Total A	0
B	Labour Charges					
1	SU/01 Front spring leaf assly. removing, dismantling, recambering and refitting / Assy.		2	Job		
2	C/01 Clutch unit complete dismantling, cleaning, checking, overhauling by replacing necessary parts		1	Job		
					Total B	0
					Total A + B	0
					SGST @ 9%	0
					CGST @ 9%	0
					Say Total	0
					Grand Total	0


P.L. Hadule

Deputy Engineer

Mechanical Subdivision No.2

Dharashiv