

Enquiry

Name of work :- Repairs Hydraulic System of Tata Hitachi 120 H No. 51573

Sr. No.	Description		Qty	Unit
1	2	3	4	5
	Repairs Hydraulic System of Tata Hitachi 120 H No. 51573 as per OEM specification given below.			
A	Cost of Spares			
1	4296276	Hose (Arm Group)	1	No.
2	4260127	Hose (Boom Group)	1	No.
B	Cost of Labour			
1	Removing & refitting high pressure hose assly. (H/06)		2	Job
	<i>Total Rs.</i>			
	<i>Add GST</i>			
	<i>Grand Total Rs.</i>			



(G.S.Giram)

Deputy Engineer

Mech. Sub Division (L.T.P.),

Latur