


Name of work : **Repair & reconditioning to Loader Lift Cylinder Assly of CASE 770 Loader Backhoe No MH 24 AJ 7847**

Sr. No.	Part Details		QTY	Rate	Amount	AMOUNT	
	Part Number	Description				GST %	Total
	Repair & reconditioning to Loader Lift Cylinder Assly of CASE 770 Loader Backhoe No MH 24 AJ 7847 by removing unservicable parts and replacing with new parts as per OEM specifications						
A	Cost of Spares Charges						
1	DC7307-650	SEAL KIT ,LIFT CYL - OLD DS102(47570731)	2	Kit			
2	DC07307-0701OA	BUSH HEAD END LOADER LIFT	2	No			
3	DC07307-0702OA	BUSH ROD END LOADER LIFT	2	No			
4	DC07306-400ZA	GLAND-	2	No			
5	85826086	HOSE - (Spool to Lift Cylinder)	2	No			
6	85813363	HOSE (Head End Lift Cylinder)	2	No			
4	85813380	HOSE	2	No			
5	85819062	HOSE SIDE SHIFT	1	No			
6	85819063	HOSE BUCKET ROD END	1	No			
	85819064	HOSE SIDE SHIFT	1	No			
7	85819065	HOSE DIPPER HEAD END	1	No			
	Sub Total of A Rs.						
B	Cost of Labour Charges						
1	Removing Loader Lift cyl. Assly from machine & refitting after repair		2	Job			
2	Dismantling of Cylinder assly ,cleaning , inspection & replacement of seal with test and trial.		2	Job			
3	Eye end rebuilding & making to STD Size		2	Job			
4	Cylinder barrel end bushing replacement		2	Job			
5	Removing and refitting high pressure hose assly		10	Job			
	Sub Total of B Rs.						
	Sub Total of (A + B) Rs.						
	Grand Total						


 (G. S. Giram)
Deputy Engineer
 Mechanical Subdivision(LTP) Latur