

Work Details

Name of work : Repairs to Swing Device of TATA Hitachi Zx120H No 51573.

Sr. No.	Part Details		Qty/Unit		Rate	Total
	Part Number	Description				
	Repairs to Swing Device of Tata Hitachi 120H No.51573 by removing Swing device assly. from machine cleaning,inspecting all parts and removing damaged spares and refitting assly. to machine by using new as per O.E.M.specification and part No.given below .					
A	Providing & fitting following spares as per OEM Specification					
1	4667150	Bearing Roller	1	No		
2	4411143	Seal Oil	1	No		
Total of Spares Rs.						
B Labour Chagges						
1	A/12	Overhauling of swing motors by dismantling, cleaning and inspection of parts, reassembling etc.	1	Job		
Total of Labour Rs :						
Total (Spares + Labour) Rs :						
CGST 9%						
SGST 9%						
Grand Total Rs :						
Round Off Rs :						



(G.S.Giram)

Deputy Engineer

Mechanical Subdivision (LTP),
Latur