

Work Detail's

**Name of work : Repairs To Track Motor, Gear Box (R.H.) Side of JCB JS 80
No.109482**

Sr.	Description		Qty	Unit	Rate	Amount
1	2		3	4	5	6
Repairs To Track Motor, Gear Box (R.H.) Side of JCB JS 80 No.109482 as per OEM specification						
A	Cost of Spare Parts					
1	20/950725	COVER ASSY.	1	No		
2	20/950726	PAD	1	No		
3	20/950739	NUT	1	No		
4	20/950730	SUN GEAR (JS75	1	No		
5	20/950734	NUT	1	No		
6	20/950737	SPACER (JS75)	1	No		
7	20/950736	SPACER (JS75)	1	No		
8	20/950741	RING CENTERING	1	No		
9	20/950738	SEAL O RING (JS75)	1	No		
10	20/950727	CIRCLIP (JS75)	1	No		
11	20/950732	CIRCLIP (JS75)	4	No		
12	826/10697	BOLT TRACK	48	No		
13	229/00751	PRESSURE HOSE	1	No		
Total A						0
B	Cost of Labour Charges					
1	A/11	Overhauling of track motors by dismantling, cleaning and inspection of parts, reassembling etc.	1	Job		
Total B						0
Total A + B						0
SGST 9%						0
CGST 9%						0
Grand Total						0
Say Amount						0


Deputy Engineer
Mechanical Subdivision No.2,
Dharashiv