

ENQUIRY

Name of work : *Repair to Idler Wheel & Supply of Bucket Pin of JCB JS 140
Hyd. Excavator No. 2439381*

Sr. No.	Part Details		Qty.	
	Part Number	Description		
	Repair to Idler Wheel & Supply of Bucket Pin of JCB JS 140 Hyd. Excavator No. 2439381 by replacement of worn out parts with new one as per OEM specification and part.			
A	Providing & fitting following spares as per OEM Specification			
1	JNA0230	Bush	2	Nos.
2	JNA0227	Kit Seal	1	Nos.
3	JNA0231	Hub	1	Nos.
4	JNA0232	O Ring	2	Nos.
5	JNA0235	Ring Snap	2	Nos.
7	JRA0226	Plug	1	Nos.
8	JRA0227	O Ring	1	Nos.
9	JNV0087	PIN Pivot	1	Nos.
11	KAV0743	Ring	2	Nos.
12	32/925214	Filter Assembly Servo	1	No.
B	Cost of Labour Charges			
1	UC/08	Removing worn out Gun Metal bushing of Idler assy. & Fitting new one	1	Job
2	UC/09	Repair to Inner Bore of Idler by welding & turning to std.size,Bore tapping etc.	1	Job
3	UC/01	Dismantling Track Chain by removing master Pin / Master Link Bolts	1	Job
4	H/02	Hydraulic Pump overhauling	1	Job
	Sub Total B			
	Add GST @ 18 %			
	Total of B Rs.			
	Total (A+B)			
	Say Total			


G.S.Giram
Deputy Engineer
Mech. Sub Division (L.T.P)
Latur