

Work Details

Name of work : Repairs To Upper Roller & Lower Roller of Tata Hitachi 120 H No.52474

Sr. No.	Description	Part No	Qty	Unit	Rate	Amount
1	2	3	4	5	6	7
	Repairs To Upper Roller & Lower Roller of Tata Hitachi 120 H No.52474					
A	Spare Parts					
1	TD03767/1	CARRIER ROLLER BRACKET	1	No		
2	TD03767/2	CARRIER ROLLER SHAFT	2	No		
3	TD03767/6	PLATE	1	No		
4	TD03767/7	CARRIER ROLLER COVER	1	No		
5	TD03767/11	HEX SOCKET HEAD SCREW	3	No		
6	TD03767/12	BRONZE BUSH	1	No		
7	J921235	BOLT	8	No		
8	TD03769/2	ROLLER END COLLAR	1	No		
9	TD03769/3	ROLLER SHAFT	3	No		
10	TD03769/5	SPRING DOWEL	6	No		
11	TD03769/9	ROLLER END COLLAR-PLUG SIDE	3	No		
12	4227029	BOLT	30	No		
Total A						0
B	Labour Charges					
1	UC/11 Rebuilding of idler shaft by welding, machining to std. size & case hardening		2	Job		
2	UC/06 Rebuilding of track roller shaft by welding & machining to std. size		3	Job		
Total B						0
Total A+B						0
SGST @ 9%						0
CGST @ 9%						0
Say Total						0
Grand Total						0


P.L. Hadule
Deputy Engineer
Mechanical Subdivision No.2
Dharashiv