


Enquiry

Name of work : Repair to Pilot (11), Return (1) & Drain Piping of Tata Hitachi Zx120-51573.

Sr. No.	Part Details		Quantity / Unit	
	Part Number	Description		
Repair to Pilot (11), Return (1) & Drain Piping of Tata Hitachi Zx120-51573 by way of supplying Following Spare parts as per OEM Specification & part number given below.				
A	Providing & fitting following spares as per OEM			
1	4460593	HOSE	1	No
2	7037064	PIPE	1	No
3	4430533	HOSE	1	No
4	9194322	HOSE	1	No
5	4187308	O-ring	2	No
B	Labour Charges (as per Mechanical Job work Schedule			
1	H/06	Removing and refitting high pressure hose assembly	4	No
Total Rs.				
CGST 9%				
SGST 9%				
Total Rs.				
Say Total (B)Rs.				
Grand Total (A+B)				


(G.S.Giram)
Deputy Engineer
Mechanical Subdivision(LTP) Latur