

Enquiry

**Repairs to Boom Cylinder Assly. (R.H. and L.H. Side) & Hydraulic
Name of work : system (Boom Cylinder Line Group) of BEML BE 200 Excavator No.
10076**

Sr. No.	Part Details		Qty.		
	Part Number	Description			
	1. 1. Repairs to boom cylinder Assly (R.H. & L.H. Side) of BEML BE 200 Es. No. 10076 by removing Boom Cylinder Assly From machine, cleaning and dismantling, checking the boom cylinder Assly. And replacing and Fitting following seal kit & pipe Assly as per OEM. specification and given number				
A	Providing & fitting following spares as per OEM Specification				
1	781 HC 03061	Seal Kit	2	No	
B	Cost of Labour Charges				
1	H/08	Removing boom jack assly. from machine and refitting after repairs	2	Job	
2	H/09	Dismantling of jack assly., cleaning, inspection and replacement of seals with test & trial	2	Job	
	Sub Total B				
	Add GST @ 18 %				
	Total of B Rs.				
	Total (A+B)				
	Say Total				


G.S.Giram
Deputy Engineer
Mech. Sub Division (L.T.P)
Latur