

Enquiry

Name of work : Door glass replacing Tata Hitachi Zx120-51573.

Sr. No.	Part Details		Quantity / Unit	
	Part Number	Description		
Repairs to TATA Hitachi Zx120-51573 by way supplying glass as per OEM Specification & part number given below.				
A	Providing & fitting following spares as per OEM Specification			
1	4602563	Glass:4448307	1	No
B	Labour Charges (as per Mechanical Job work Schedule Rate 2019-2020)			
1	BD/09	Door glass regulator machine replacing / Door (Equivalent to Tata SK1613)	1	No
Total Rs.				
CGST 9%				
SGST 9%				
Total Rs.				
Say Total (B)Rs.				
Grand Total (A+B)				

(G.S.Giram)
Deputy Engineer
Mechanical Subdivision(LTP) Latur