Enquiry

Name of work : Repairs to Arm Cylinder Assly & Hydraulic System of BEML BE-200 Ex.No.10076

Sr No	Part No	Description	Qty	Unit	Rate	Amount
		Repairs to Arm Cylinder Assly & Hydraulic System of BEML BE-200 Ex.No.10076 by removing Arm Cylinder Assly From machine, Cleaning and dismanting, Checking the Arm Cylinder Assly & Hydraulic System and replacing and Fitting following seal kit & pipe Assly as OEM Specifications and part No.given below.				
1	781нс03086	Seal kit.	1	No.		
2	781РН02425	Pipe Assly.(L.H.Side).	1	No.		
3	781РН02563	Pipe Assly.	1	No.		
					pares Rs.	
		(A) Total cost of			pare parts	
В	Cost of Labour Charges					
4	Н/08	Removing Boom jack assly from machine and refitting after replairs	2	No.		
5	Н/09	Dismanting of jackassly.,cleaning,inspection and replacement of seals with test & trial	2	No.		
6	Н/06	Removing & refitting high pressure hose assembly	2	No.		
			(B) C	ost of I	abour Rs.	
GST 18%						
(B) Total cost of Labour including GST (A+B) Grand Total Rs.						
Say Rs.						

(G.S.Giram)
Deputy Engineer
Mechanical Sub Division (LTP),
Latur