

ENQUIRY

Name of work : ***Repair to Hydraulic system (Side branch piping ,Delievery piping) Tata Hitachi Zaxis 120 Excavator No. 51573***

Sr. No.	Description		Qty	
	Repair to Hydraulic system (Side branch piping ,Delievery piping) Tata Hitachi Zaxis 120 Excavator No. 51573 by removing old & damaged burst leaked Hyd.Hose from machine & replacing fitting new Hyd.Hose as per OEM specification & part no.given below with test and trial @ site.			
A	Cost of Spares Charges			
1	4285801	HOSE	1	No
2	4250063	HOSE	1	No
3	4455403	HOSE	1	No
B	Cost of Labour Charges			
1	H / 06	Removing & refitting high pressure hose assly.	3	Job



G.S.Giram
Deputy Engineer
Mech. Sub Division (L.T.P)
Latur