

WORK DETAILS

Name of work : Repair & Reconditioning Swing Motor Assy of Tata Hitachi 120 Hydraulic Exc No. 52806

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repair & Reconditioning Swing Motor Assy Assly of Tata Hitachi 120 Hydraulic Exc No. 52806by removing the Swing Motor Assy assly from machine,dismentling ,checking and removing unservicable parts & replacing by new spares . Also removing bushing of assly & replacing by new spares as per OEM Specification					
A	Providing & fitting following spares as per OEM Specification					
1	4320490	Seal Oil	1	No.		
2	4396102	Plate Swash	1	No.		
3	4413768	Bearing Needle	1	No.		
4	3087818	Plate Friction	4	No.		
5	4413765	O' ring	1	No.		
6	4413764	O' ring	2	No.		
7	3081727	Retainer	1	No.		
8	3075729	Plate	4	No.		
9	A590916	Washer Spring	4	No.		
B	LABOUR CHARGES					
1	Overhauling of swing motor by dismantling ,cleaning & inspection of parts		4	Job		
					GST 18%	
					Total Rs	



Deputy Engineer
Mechanical Subdivision, Latur