

Work Details

Name of work : Repairs & Reconditioning to Jack Assembly of TATA Hitachi Zx 220 No. 305

Sr. No.	Description	Qty	Unit	Rate	Amount
1	2	3	4	5	8
1	Repairs & Reconditioning to Jack Assembly of TATA Hitachi Zx 220 No. 305 by removing dismantling & refitting jack assembly				
2	Providing & refitting following spares parts as per OEM Specification given below.				
1	TE 07941 - Seal Kit	1	No.		
2	TC 007394/10 Bush	1	No.		
3	TC 01398/14 - Pipes	1	No.		
	Cost of Spare Rs :-				
B	Cost of Labour				
1	Removing bucket/arm/boom jack assly. from machine and refitting after repairs.	1	Job		
2	Dismantling of jack assly., cleaning, inspection and replacement of seals with test & tria.	1	Job		
3	Eye end rebuilding & making to STD size.	1	Job		
	Cost of Labour Rs :-				
	Total Spares + Labour Rs :-				
	CGST @ 9% Rs :-				
	SGST @ 9% Rs :-				
	Grand Total Rs :-				
	Round Off Rs :-				



(S.S.Garad)

Deputy Engineer

Mechanical Subdivision No. 3,
Dharashiv