

Work Details

Name of work :- Repair & Reconditioning to Valve Pilot (Travel) Of TATA Hitachi Zx 220 No. 306

Sr. No.	Description	Qty	Unit	Rate Rs	Amount
1	2	3	4	5	6
	Repair & Reconditioning to Valve Pilot (Travel) Of TATA Hitachi Zx 220 No. 306 following spares parts as per OEM Specification of given below.				
A	Cost of Spares Charges				
1	9226367	4	No.		
2	4319299	4	No.		
3	4368629	4	No.		
4	4364970	4	No.		
5	4368630	4	No.		
6	4425305	2	No.		
7	J781030	2	No.		
8	A590910	2	No.		
9	4437432	2	No.		
10	4428902	2	No.		
11	A590906	4	No.		
				Total of Spares Rs :-	
B	Cost of Labour Charges				
1	H/01 Removing Hydraulic / Steering pump from machine & refitting on machine	1	Job		
2	E/46 Radiator chock up removing by cleaning all the tubes, soldering the tubes with top & bottom removing and refitting	1	Job		
				Total of Labour Rs :-	
				Total Spares+Labour Rs :-	
				CGST 9 % Rs :-	
				SGST 9 % Rs :-	
				Grand Total Rs :-	
				Round Off Rs :-	

(A.G.Kalkumbe)
Section Engineer
Mechanical Subdivision No.2,
Dharashiv

(P.L.Hadule)
Deputy Engineer
Mechanical Subdivision No. 2,
Dharashiv