


Work Detail's

Name of work :- Repair & Reconditioning to Swing Motor Assly Of TATA Hitachi Zx 220 No. 306

Sr. No.	Description	Qty	Unit	Rate Rs	Amount
1	2	3	4	5	6
	Repair & Reconditioning to Swing Motor Assly Of TATA Hitachi Zx 220 No. 306 following spares parts as per OEM Specification of given below.				
A	Cost of Spares Charges				
1	4411535	1	No.		
2	A811120	1	No.		
3	4187590	1	No.		
4	3084729XXXTC	1	No.		
5	4336929	4	No.		
6	4404506	2	No.		
				Total of Spares Rs :-	0.00
B	Cost of Labour Charges				
1	A/12 Overhauling of swing motors by dismantling, cleaning and inspection of parts, reassembling etc.	1	Job		
				Total of Labour Rs :-	0.00
				Total Spares+Labour Rs :-	0.00
				CGST 9 % Rs :-	0.00
				SGST 9 % Rs :-	0.00
				Grand Total Rs :-	0.00
				Round Off Rs :-	0.00


 (P.L.Hadule)
 Deputy Engineer
 Mechanical Subdivision No. 2,
 Dharashiv