Work Details

Name of work: Repair to Main Piping of TATA Hitachi Zx 220 No. 306

Sr. No.	Description		Qty	Unit	Rate Rs	Amount
1	2	3	4	5	6	7
		Hitachi Zx 220 No. 306 by repairs to EM Specification of given below.				
A	Cost of Spares Charges				5	
1	8125290	Pipe	1	No.		
2	4153488	CLAMP;PIPE	2	No.	i	
3	J271285	BOLT; SEMS (offer J901285 +A59	1	No.	,	•
4	J271270	BOLT; SEMS	1	No.		
5	4187308	O-RING 1BAS568	8	No.		
6	YA60027640T1	ASSY HOSE	2	No.	1	
7	4648966	HOSE	2	No.		
8	4189539	ADAPTER; S	2	No.		
	Total of Spares Rs :-					
В	Cost of Labour Charges					
1	Removing & refitting high press	sure hose assly. H/06	5	Job		
	Total of Labour Rs :-					
	Total Spares+Labour Rs :-					
	CGST 9 % Rs :-					
	SGST 9 % Rs :-					
	Grand Total Rs :-					
	Round Off Rs :-					

(P.L.Hadule)

Deputy Engineer

Mechanical Subdivision No. 2,

Dharashiv