


Work Details

Name of work :- Repair & Reconditioning to Delivery & Return Piping Of TATA Hitachi Zx 220 No. 306

Sr. No.	Description	Qty	Unit	Rate Rs	Amount
1	2	3	4	5	6
	Repair & Reconditioning to Delivery & Return Piping Of TATA Hitachi Zx 220 No. 306 following spares parts as per OEM Specification of given below.				
A	Cost of Spares Charges				
1	YA00004043	Hose	1	No.	0.00
2	4393146	Hose	1	No.	0.00
3	4085560	FLANGE;SPLIT	6	No.	0.00
4	Z966993	O-RING;1BAS568-	4	No.	0.00
5	J901290	BOLT	1	No.	0.00
6	9773142	BRACKET	1	No.	0.00
7	7060664	PIPE;RETURN	1	No.	0.00
8	A885006	PLUG	1	No.	0.00
9	4506424	O-RING	1	No.	0.00
10	A885003	PLUG-3/8 X 21	1	No.	0.00
11	A885008	PLUG	1	No.	0.00
12	4506429	O-RING	1	No.	0.00
13	8098385	BRACKET	1	No.	0.00
14	J901030	BOLT M10X030.0	1	No.	0.00
15	J222010	WASHER M10	1	No.	0.00
16	4053698	CLAMP;PIPE 43X1	1	No.	0.00
17	J271270	BOLT; SEMS	1	No.	0.00
18	J901270	BOLT M12X70	1	No.	0.00
19	4712342	COUPLING (OFFER 4067834)	1	No.	0.00
	Total of Spares Rs :-				
	0.00				
B	Cost of Labour Charges				
1	H/06 Removing & refitting high pressure hose assly.	2	Job		0.00
	Total of Labour Rs :-				
	0.00				
	Total Spares+Labour Rs :-				
	0.00				
	CGST 9 % Rs :-				
	0.00				
	SGST 9 % Rs :-				
	0.00				
	Grand Total Rs :-				
	0.00				
	Round Off Rs :-				
	0.00				


 (P.L. Hadule)
 Deputy Engineer
 Mechanical Subdivision No. 2,
 Dharashiv