


Name of Work : Repairs to Mahindra Bolero Pick No. MH 25 P 5123

Sr.No	Description of Job	Qty.
A	Repair & reconditioning Gear BOx, Differential, Leaf to Mahindra Bolero Pick No. MH 25 P 5123	
1	0912593 – Bush Pivot End	1 No
2	0703SS1350N – Out put shaft for NGT520WD	1 No
3	0703DD2740N – 3 rd Gear Assly V4 NGT 520	1 No
4	0703ED1020N – Synchronizer pack assly 3 rd 4 th NGT520	1 No
5	9603489380 – Gear driven reverse	1 No
6	0703DD1530N – Circlip input gear for NGT520	1 No
7	0703DD1540N – Belleville washer MD GR BRG FR NGT 520	1 No
8	0703DD1590N – BRG DGBBC/S FRONT END 6305 NGT 520	1 No
9	0703DD1620N – BLRBRG IP GEAR DIA 20*DIA28*	1 No
10	0703DD1890N –SNAP RING SP80 For bearing NGT520	1 No
11	10703DD1880N – Bearing FR NGT 520 6307 2RSRNC3	1 No
12	0703DD1600N – BRG C/S REAR END CRB NGT520	1 No
13	0703DD1600N- Sub shaft BRG 6304 2 RSRC3 FR NGT 520	1 No
14	GO01 – Local spare part oil & AC gas gearil	1 No
15	0703DD4940N – Assly input ger V4	1 No
16	0703DAA00140N – Shaft counter rear	1 No
17	0703EAD01380N – Synchro assly 1 st 2 nd Dual cone 5MT320	1 No
18	0401AAA02680N – Leaf spring assly Rear	1 No
19	0703AD09320N – Shaft counter	1 No
20	0703DAD08780N – Gear assly Second	1 No
B	Labour Charges	
1	(G/01) – Gear Box removing by removing releted assly & fitting for repair	1 Job
2	(D/01) - Differential complete overhauling by removing damaged part & fitting	1 Job
3	(SU/01) - Front spring assly removing dismentaling recambering and fitting assly.	1 Job


Deputy Engineer,
Mechanical subdivision no. 3,
Osmanabad