


WORK DETAILS

Name of work : *Repair & Reconditioning RH Idler Assembly, Hoses Assly of JCB JS 140 No 2439384*

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repair & Reconditioning RH Idler Assembly, Hoses Assly of JCB JS 140 No 2439384 by removing the assly from machine,dismentling , checking and removing unservicable parts & replacing by new spares . Also removing bushing of assly & replacing by new spares as per OEM Specification					
A	Providing & fitting following spares as per OEM Specification					
1	331/20124	PISTON	1	No.		
2	331/20045	YOKE IDLER	1	No.		
3	624/80025	HOSE ASSLY Center Joint to L.H.Side traviling device	2	No.		
4	229/00317	HOSE ASSLY	1	No.		
5	550/43375	HOSE ASSLY	1	No.		
6	229/00315	HOSE ASSLY	1	No.		
B	LABOUR CHARGES					
1	Dismantling Track chain by removing Master Pin / Master Link bolts		1	Job		
2	Removing and refitting of idler assly		1	Job		
3	Reassembling of track chain & fitting of master pin by hydraulic press.		1	Job		
4	Rebuilding of idler shaft by welding, machining to std. size & case hardening		1	Job		
5	Removing & refitting high pressure hose assembly		5	Job		
					GST 18%	
					Total Rs	



Deputy Engineer
Mechanical Subdivision, Latur