

WORK DETAILS

Name of work : Repair & Reconditioning LH Track Chain Assly of JCB JS 140 Hydraulic Excavator No 2439384

Sr. No.	Part Details		Qty	Rate	Amount		
	Part Number	Description					
	Repair & Reconditioning LH Track Chain Assly of JCB JS 140 No 2439384 by removing the assly from machine, dismantling ,checking and removing unservicable parts & replacing by new spares . Also removing bushing of bucket link assly & replacing by new spares as per OEM Specification						
A	Providing & fitting following spares as per OEM Specification						
1	331/17176	Link Track RH	7	No			
2	331/17177	Link Track	7	No			
3	331/21733	Bush Track	8	No			
4	331/21731	Seal Dust	5	No			
5	JNJ0062	Hose	1	No			
6	JBV0515	Hose	1	No			
7	JLJ0299	Hose	1	No			
B	LABOUR CHARGES						
1	Dismantling Track chain by removing Master Pin / Master Link bolts		1	Job			
2	Removing and replacing link/ Bush		8	Job			
3	Reassemble track chain by fitting master pin		1	Job			
4	Removing & refitting high pressure hose assembly		3	Job			
GST 18%							
Total Rs							



Deputy Engineer
Mechanical Subdivision, Latur