

WORK DETAILS

Name of work : Repairs & reconditioning to Mahindra Traco Transporter 35Ton-MH25U1379 by way of Supplying CLUTCH DISC ASSEMBLY, Filters & Lamps etc. & Also Hub greasing of all Wheels.

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repairs & reconditioning to Mahindra Traco Transporter 35Ton-MH25U1379 by way of supplying CLUTCH DISC ASSEMBLY, Filters & Lamps etc. & Also Hub greasing of all Wheels. with new parts as per OEM Specification.					
A	Providing & fitting following spares as per OEM Specification					
1	6801AAP00012N	CLUTCH COVER ASSEMBLY DIA 395MM	1	No.		
2	6801BAU00021N	CLUTCH DISC ASSEMBLY DIA 395 mm	1	No.		
3	6802AAP00031N	BEARING CLUTCH RELEASE	1	No.		
4	6402BAN00060N	SAFETY ELEMENT	1	No.		
5	7005AAP00071N	SEAL OUTER	8	No.		
6	0303BAV00510N	LUBE FILTER SPIN ON	1	No.		
7	0305DAV00350N	FUEL FILTER PAPER ELEMENT	1	No.		
8	7601BAP00100N	HUB CAP GASKET	2	No.		
9	7306AAP00040N	FILTER CARTRIDGE WATER SEPERATOR	1	No.		
10	7005BAP00021N	Gasket	4	No.		
11	SF0901021	PIN COTTER 8mmX80mm	4	No.		
12	7901CAP00031N	FRONT TOP MARKER LAMP-RH	1	No.		
13	7901CAP00021N	FRONT TOP MARKER LAMP-LH	4	No.		
14	7901BAP00211N	FRONT TURN INDICATOR LH	1	No.		
15	7901BAP00201N	FRONT TURN INDICATOR RH	1	No.		
B	LABOUR CHARGES					
1	Clutch unit complete dismantling, cleaning, checking, overhauling by replacing necessary parts		1	Job		
2	Clutch pressure plate facing		1	Job		
3	Fuel tank opening cleaning, brazing & refitting		1	Job		
4	Front wheel hub greasing including oil seal changing / No.		2	Job		
5	Rear wheel hub greasing including oil seal changing / No.		6	Job		
					GST 18%	
					Total Rs	



Deputy Engineer
Mechanical Subdivision, Latur