Work Details

Name of work : Repair to Control Valve Assly and Hydraulic System of Kobelco SK 140 No. 420

Part Details Sr. No.		Otv	/ Unit	Rate	Total
Part Number	Description				
Repair to Control Valve Assly by replacing following damage parts.					
A Cost of Materials					
Valve Solenoid YN35V00054F1		1	No		
B Cost of Labour Charges					
Control Valve Overhauling (H/06)		1	Job		
C Repairs to Ider Assembly by replacing following parts					
A Cost of Materials					
Hose Assembly ZX22M08180		1	No		
Hose Assembly ZX33M04230		2	No		
B Cost of Labour Charges					
1 Removing & refitting high pressure hose assly. (H/06)		3	Job		
Total Rs :					
CGST 9%					
	Repair to Control Valve Assly by reparts. Cost of Materials Valve Solenoid YN35V00054F1 Cost of Labour Charges Control Valve Overhauling (H/06 Repairs to Ider Assembly by repairs to Ider Assembly by repairs to Ider Assembly SX22M08180 Hose Assembly ZX23M04230 Cost of Labour Charges	Repair to Control Valve Assly by replacing following damage parts. Cost of Materials Valve Solenoid YN35V00054F1 Cost of Labour Charges Control Valve Overhauling (H/06) Repairs to Ider Assembly by replacing following parts Cost of Materials Hose Assembly ZX22M08180 Hose Assembly ZX33M04230 Cost of Labour Charges	Repair to Control Valve Assly by replacing following damage parts. Cost of Materials Valve Solenoid YN35V00054F1 1 Cost of Labour Charges Control Valve Overhauling (H/06) 1 Repairs to Ider Assembly by replacing following parts Cost of Materials Hose Assembly ZX22M08180 1 Hose Assembly ZX33M04230 2 Cost of Labour Charges	Repair to Control Valve Assly by replacing following damage parts. Cost of Materials Valve Solenoid YN35V00054F1 1 No Cost of Labour Charges Control Valve Overhauling (H/06) Repairs to Ider Assembly by replacing following parts Cost of Materials Hose Assembly ZX22M08180 Hose Assembly ZX33M04230 Cost of Labour Charges Removing & refitting high pressure hose assly. (H/06) Grand	Repair to Control Valve Assly by replacing following damage parts. Cost of Materials Valve Solenoid YN35V00054F1 Cost of Labour Charges Control Valve Overhauling (H/06) Repairs to Ider Assembly by replacing following parts Cost of Materials Hose Assembly ZX22M08180 Hose Assembly ZX33M04230 Cost of Labour Charges Removing & refitting high pressure hose assly. (H/06) Total Rs:

(S.S.Garad)

Deputy Engineer

Mechanical Subdivision No. 3,

Dharashiv