


Work Details

Name of work :- Repair to Arm jack of TATA Hitachi 120 H Ex No. 52475

Sr. No.	Description		Qty	Unit	Rate Rs	Amount
1	2	3	4	5	6	7
	Repair to Arm jack assly of TATA Hitachi 120 H Ex No. 52475 by inspecting jack, dismantling from machine, cleaning & replacing unservicable parts as per OEM Specification of given below.					
A	Cost of Spare Parts					
1	TC01376/40	Seal Kit	1	No.		
2	3091719	Pipe	1	No.		
3	3091735	Pipe	1	No.		
	Total of Spares Rs :					
B	Cost of Labour Charges					
1	Removing bucket/arm/boom jack assly. from machine and refitting after repairs.		1	Job		
	Total of Labour Rs :					
	Total Spares+Labour Rs :					
	CGST 9 % Rs :					
	SGST 9 % Rs :					
	Grand Total Rs :					
	Round Off Rs :					



(S.S. Garad)

Deputy Engineer

Mechanical Sub Division No.3,
Dharashiv