

ABSTRACT

name of work :-

repairs to swing bearing of Tata hitachi zaxis 120 H Ex. Sr no 52466.

Rate Analysis

Sr.No	Particulars	Qty	Rate	Amount
1	repairs to swing bearing of Tata hitachi zaxis 120 H Ex. Sr no 52466.			
	cost of spare parts	1	39184	39184
	cost of labour	1	3174	3174
			Total	42358
			add 18% GST	7624.4
			Grand Total	49982.4
			Say	49982

A. Lingare

A.E.II

Mech subdivision No. 3,
Osmanabad

Sanjay D

Deputy Engineer

Mechanical subdivision No. 3,
Osmanabad

[Signature]
Deputy Engineer
Mechanical subdivision No. 3,
Osmanabad

MEASUREMENT

ame of work :-

repairs to swing bearing of Tata hitachi zaxis 120 H Ex. Sr no 52466.

Rate Analysis

Sr No	Particulars	Qty	Rate	Amount
1	swing bearing i.e. round table. bolts. balls & seal replacing A i3, 26	1	3174	3174
2	replacing and fitting following damaged spares			
2.1	4425980 pin knock	1	116	116
2.2	J931695 bolt	36	165	5940
2.3	4272297 packing	1	50	50
2.4	4483676 seal	1	4824	4824
2.5	4127708 support	10	530	5300
2.6	4289757 seal (new:4634010)	1	8802	8802
2.7	4315493 seal (new:4634010)	1	8802	8802
2.8	4428919	10	535	5350
			Total	42358
			add 18% GST	7624.4
			Grand Total	49982.4
			Say	49982

A. E. II

A.E.II

Mechanical subdivision No. 3,
Osmanabad

Deputy Engineer

Deputy Engineer

Mechanical subdivision No. 3,
Osmanabad